

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re the application of

LAP-SUN HUI

Patent No.: 6,863,108 B1

Issued: March 8, 2005

Serial No: 10/765,747

Filed: January 27, 2004

For: REINFORCING RING APPLICATOR

Examiner: James D. Sells

Group Art Unit: 1734

Client ID/Matter No: JOUI 66790

May 13, 2005

Los Angeles, California 90045

REQUEST FOR CERTIFICATE OF CORRECTION

Certificate of Corrections Branch Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

Dear Sir:

The above-identified patent has been found to have the errors set forth in the enclosed Certificate of Correction. It is requested that this Certificate of Correction be issued and returned to us. Since these errors occurred in both the final printing phase of the patent and in the final application, a check in the amount of \$100.00 is enclosed to cover the necessary fees. Should the Office determine that additional fees are needed, please charge Deposit Account No. 06-2425.

The errors are verifiable in the patent application file as follows:

ERROR

VERIFICATION

Title page and drawing sheets 1 through 6, replace informal drawings with formal drawings.

Formal drawings. See Attachment A.

Column 2, line 23, delete "method" and insert --methods--.

Applicant error.

Column 2, line 46, delete "mount".

Applicant error.

Column 2, line 50, delete first occurrence of "of the".

Applicant error.

Column 3, line 49, delete "cooperated" and insert --cooperate--.

Applicant error.

Column 3, line 50, delete "shat" and insert -- shaft--.

Applicant error.

Column 4, line 23, delete "party" and insert --partly--.

Applicant error.

Column 4, line 62, delete "attached" and insert --attach--.

Applicant error.

Column 4, line 62, delete "hold" and insert --hole--.

Applicant error.

Column 4, line 67, delete "hold" and insert --hole--.

Applicant error.

Column 5, lines 1, 4, and 5 delete "hold" and insert --hole--.

Applicant error.

Column 5, line 6, delete "interact maintain" and insert --interact to maintain--.

Applicant error.

Column 5, line 14, delete "nut for" and insert --nut 40--.

Applicant error.

Column 5, line 39, after "strike plate 80" delete comma and insert --.-- (a period).

Applicant error.

Column 7, line 33, delete "time" and insert --end--.

Applicant error.

Column 7, line 38, delete "tom" and insert --torn--.

Printing error.

Column 8, line 31, delete "bottoms".

Applicant error.

Column 10, line 52, delete "coller" and insert --collar--.

Applicant error.

Column 11, line 3, delete "configured" and insert --configured to--.

Applicant error.

Column 11, line 10, delete "reinforces" and insert --reinforcer--.

Applicant error.

Column 11, line 37, delete "mount".

Applicant error.

Column 12, line 46, delete "cooperated" and insert --cooperate--.

Applicant error.

Column 12, line 46, delete "shat" and insert Applicant error. --shaft--.

These errors occurred in good faith and correction thereof does not involve such changes in the patent as would constitute new matter or would require re-examination. It is requested that a Certificate of Correction be issued and returned to us.

Attached hereto, in duplicate, is Form PTO-1050, with at least one copy being suitable for printing.

A duplicate of this document is attached.

Respectfully submitted,

FULWIDER PATTON LEE & UTECHT, LLP

By:

John K Fitzgerald

Registration No. 38,881

JKF:ck

Howard Hughes Center 6060 Center Drive, Tenth Floor Los Angeles, CA 90045 Telephone: (310) 824-5555

Facsimile: (310) 824-9696

Customer No. 24201

89109.1